



WORK ORDER

Bureau of Agricultural Research

RDMIC Bldg. Elliptical Rd. Corner Visays Ave. Diliman Q.C.

COMMISSION ON AUDIT
BUREAU OF AGRICULTURAL RESEARCH

RECEIVED

Client: TOYOTA NORTH EDSA
Address: 1010 EDSA, Quezon City
VIN: 000-300-956-061

WO No: _____
Date: _____
BY: 9/27/2012
gob...

Gentlemen:

Please furnish this office the following articles subject to the terms and conditions contained herein.

Place of Delivery: Bureau of Agricultural Research RDMIC Bldg. Elliptical Rd., Delivery Term: 14 Working Days
Date of Delivery: _____ Payment Term: gov't Check

Item No.	Unit	Quantity	Description	Unit Cost	Amount
1			Perform 180,000 kms check-up		1,780.80
		7	Fully Synthetic Oil	638.99	4,472.93
		1	Gasket <i>(SILICONE)</i>	31.11	31.11
		1	Oil Filter	425.60	425.60
		1	SCV Kit (Sunction Valve)	5,777.59	5,777.59
		1	Front Shock Absorber LH	3,690.52	3,690.52
		2	End Sub Assy, Steering <i>(RACK END)</i>	6,346.04	12,692.08
		1	Spiral Cable	12,806.27	12,806.27
		1	Support Sub Assy, Front	3,838.55	3,838.55
			XIR		1,120.00
			TIPTOP		1,568.00
			Engine Detailing		1,090.00
		1.0	Multi Cleaner	415.00	415.00
		1.0	Miscellaneous-2	170.00	170.00
2			Inspect Airbag Warning		784.00
3			SCV (Sunction Valve)		1,176.00
4			LH/ RH Rack-End		784.00
5			Front shock Absorber		784.00
6			Wheel Allignment		2,352.00

***** NOTHING FOLLOWS *****

Total Amount 55,758.45
Less: Discount 2,952.81